

LA-UR-22-21183

Approved for public release; distribution is unlimited.

Title: Harborview Research and Training (HRT) Facility Remediation
Project-Photos

Author(s): Mullen, Evelyn

Intended for: General Use

Issued: 2022-02-10



Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by Triad National Security, LLC for the National Nuclear Security Administration of U.S. Department of Energy under contract 89233218CNA000001. By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.

Harborview Research and Training (HRT) Facility Remediation Project - Photos

Evelyn Mullen

February 10, 2022



Removed drywall and insulation,
vacuumed surfaces in some interior
spaces




Clean area post-remediation and FSS ready for reconstruction



Attention to detail important for surveys and cleaning, including large areas and small spots



Surveys were done on all items with fans,
Biosafety Cabinets (BSCs) a focus area



LIFA vent cleaning system – cleaned ducts where possible



Approach to contaminated duct removal

Chase opened



Encapsulation



Removed



Replaced




Chemical treatment of heavily impacted surfaces



Outside Area Remediation



FSS floor-cart survey roof



Final Status Surveys (FSS) demonstrated final contamination levels were below regulatory limits



FSS and DOH Confirmatory Sampling – all areas of the building were sampled

